		-			
Site	ASE Tseung Kwan O Landing Point	Inspected By: Grace YANG			
Insp	ection Date: 7-Dec-12 Time: 16:00 - 1	7:00			
Wea	Weather				
Condition Sunny ✓ Fine Overcast Drizzle		Rain	Storm Hazy		
Temperature 19 °C Humidity High		Moderate ✓ L	LOW		
Wind Calm Light Breeze Strong					
Α	Noise	N/A or Yes not observed	No Photo/Remarks		
A1	Are all plant and equipment well maintained and in good operating condition?		See Note 1.		
A2	Is idle equipment turned off or throttled down?	√			
АЗ	Are powered mechanical equipment covered or shielded by acoustic materials?	✓			
A4	Are silenced equipment used where practicable?	√			
A5	Do mobile plants be sited as far away from NSRs as possible?	✓	No NSRs nearby.		
A6	Do plants known to emit noise strongly in one direction be oriented away from nearby NSRs?	✓	No NSRs nearby.		
A7	Major noise source(s) Traffic	✓ Construction activ	rities inside of site		
	Construction activities outside of site	Others			
A8	Any remedial action undertaken?	√			

Rev1 Page 1 of 4

Asia Submarine-cable Express (ASE) - Tseung Kwan O

В	Water Quality		N/A or not observed	Yes	No	Photo/Remarks
B1	Is drainage system adequate?		✓			B1 - B10:
	Are there temporary ditches for runoff discl	narge into appropriate				
B2	Watercourse?		✓			Silt curtain
ВЗ	With silt retention pond?		√			decommissioned as
B4	Do permanent drainage channels have:	sediment basin?	✓			construction works at the
B5		traps and baffles?	✓			seawall side finished.
B6	Are there sediment tanks for settling runoff	prior to disposal?	✓			
В7	Are there oil interceptors in drainage system	m?	✓			
В8	Oil and grease removed regularly?		\checkmark			
В9	Bypass to prevent flushing during per	iods of heavy rain?	\checkmark			
B10	Is drainage system well maintained?		✓			
B11	Is exposed earth stabilized after earthwork	s have been completed?		✓		
B12	Are exposed slope surfaces covered (by ta	rpaulin or other means)?	✓			
B13	Are open stockpiles of more than 20 m ³ co	vered during rainstorm?	✓			
B14	Are manholes covered and sealed?		✓			
	Rainy Season					
B15	Drainage system adequately designed	d for storm flow?	\checkmark			B15 & B16: Inspection
B16	Sediment control measures inspected rain storms?	I and maintained after	✓			conducted in dry season.
B17	Is debris and rubbish on site collected and	disposed of properly?		√		
B18	Is wastewater discharge license available f	or inspection?	✓			
B19	Measures to prevent the washing away of	sand/silt to drains?		√		
B20	Is there any sediment plume observed exist	sting the marine works area?			√	

Rev1 Page 2 of 4

	Environmental Complaint
1	Number of Environmental Complaint Received from 3-Dec-12 to 9-Dec-12 . 0
	General / Housekeeping N/A or Yes No Photo/Remarks not observed
1	Are potential stagnant pools cleared and mosquito breeding prevented?
	Items for Inspection
	- New beach manhole, and - Land duct construction site
	Notes / Issues Recorded On Site
	1. Dark smoke was seen rising from the crane truck used to backfill the excavated rocks and soils. The Contractor was reminded to well maintain all plants and equipment on site. Dark smoke, which indicates inefficient combustion of fuel within the plant engine should be avoided to minimise air pollution emission.

Rev1 Page 3 of 4

(Name: Grace YANG

Corrective Actions
Follow-up actions by the Contractor will be checked in next week's site inspection.
Signatures: ET:

Rev1 Page 4 of 4