



*Photo 1 – Impermeable sheets were observed to have been placed on the stockpiles of excavated soils and rocks that were not in use.*



*Photo 2 – The EP copy displayed at the vehicular site entrance was damaged.*



*Photo 3 – Dark smoke was seen rising from the crane truck used to backfill the excavated rocks and soils.*