



*Photo 1 - A silt curtain was employed around the seawall area.*



*Photo 2 - A rubbish bin was placed on site in the next day of site inspection.*



*Photo 3 - Tarpaulin sheets to cover dusty stockpiles to prevent dust generation were absent from the construction site.*



*Photo 4 - The corrective action to cover dusty materials was conducted by the Contractor in the following day of site inspection.*