



*Photo 1 - A silt curtain was employed around the seawall area.*



*Photo 2 - Fences were erected along both sides of the land duct alignment*



*Photo 3 - A rubbish bin was provided by the Contractor*



*Photo 4 - Tarpaulin sheets to cover open stockpiles to prevent dust generation were absent from the construction site.*