



*Photo 1 - A wheel-washing bay was available at the construction exit.*



*Photo 2 - Dark smoke was seen rising from the crane truck.*



*Photo 3 - Stockpiles of the excavated materials were observed to be exposed.*