



*Photo 1 - A silt curtain was employed around the seawall area.*



*Photo 2 - Tarpaulin sheets were observed to have been used to cover excavated materials for the part that was not actively used.*



*Photo 3 - A rubbish bin was provided by the Contractor.*



*Photo 4 - Dark smoke was seen rising from the crane truck used to restore large boulders to the opened sea wall.*