



*Photo 1 - A copy of EP was displayed conspicuously at the vehicular site entrance.*



*Photo 2 - A silt curtain was employed around the seawall area.*



*Photo 3 - A dip tray was provided for the generator that potentially has oil leakage.*



*Photo 4 - Portable toilet was provided on the construction site.*