



*Photo 1 – For the completed section of land duct, excavated materials have been backfilled and the site has been reinstated to its original status.*



*Photo 2 – Some stockpiles of the excavated soils from the new beach manhole and land duct were partly exposed in the rain.*