



*Photo 1 – Construction of the land duct has been finished and the site has been reinstated to its original conditions.*



*Photo 2 – Construction of the new beach manhole has been largely finished, with only small part of backfilling and reinstatement works remaining.*



*Photo 3 –The EP copy displayed at the vehicular site entrance was damaged.*